



THE FRAME, UCA, COILOVER LENGTH AND SPINDLE HAVE NOT CHANGED. THE LOCATION OF THE LCA HAS CHANGED THOUGH, VIA THE CAMBER ADJUSTMENT BOLTS. NOTE THE CHANGE IN CAMBER AS SHOWN VIA THE TIRE CENTERLINES, EXAGGERATED, OBVIOUSLY.