



SERVICE BULLETIN

Classification:

WT04-001a

Reference:

NTB04-023a

Date:

February 23, 2004

NISSAN; TIRE ROTATION AND DIAGNOSIS OF THE LOW TIRE PRESSURE WARNING SYSTEM (LTPWS)

This bulletin amends NTB04-023. Please discard all earlier versions.

APPLIED VEHICLES: All Nissan vehicles with the Low Tire Pressure Warning System

SERVICE INFORMATION

When doing a tire rotation on a vehicle with the Low Tire Pressure Warning System (LTPWS), please note:

- "ID registration" of the LTPWS **is not required**.

For 2004 Armada (TA60), 2004 Quest (V42), 2004 Titan (A60)

- In the Electronic Service Manual (ESM) for the Above Vehicles, on pages WT-13 and WT-14, it says that you need to perform ID registration when the tires are rotated. **This is not the case. As stated above, ID registration does not have to be done when rotating the tires.**
- Future amendments to these ESMs will have this change made.

IMPORTANT NOTE ABOUT LTPWS SELF-DIAGNOSIS AND CONSULT-II

Remember, as stated in the ESM:

- The first step when performing LTPWS Self-Diagnosis is to **perform transmitter ID registration**.
- This is critical or **the actual malfunction location may be different from that displayed on CONSULT-II**.